Alliance Environmental Group, Inc.

100 Jefferson Boulevard, Warwick, Rhode Island 02888
Telephone: 401.732.7600; Fax: 401.732.7670

December 15, 2008

Mr. Tom Campbell
Emergency Response Division
Rhode Island Department of Environmental Management (RIDEM)
235 Promenade Street
Providence, RI 02908

RE: Site Remediation
Former Mill Property
1 Carrington Street
Lincoln, RI

Dear Mr. Campbell,

Alliance Environmental Group, Inc. (AEG) on behalf of FDS Industries, the owner of the above-mentioned property (hereinafter, "Site"), has completed the following letter report summarizing the results of remediation efforts undertaken at the Site from June 3, 2008, to July 15, 2008 with final soil disposal on November 10, 2008. A United States Geological Survey (USGS) Locus map of the Site is attached as Figure 1.

During the above timeframe, AEG oversaw and directed the excavation and cleanup following the steps outlined in a January 7, 2008, report to RIDEM titled, "Test Pit Investigation Results." In this report, AEG outlined six steps starting with cleanup of debris on the Site and progressing through excavation and disposal of contaminated soil off-site. The approximate area of petroleum impact is outlined on the attached Figure 2 – Site Plan.

In early June 2008, a demolition company removed the former boiler room located on the eastern edge near the petroleum-impacted area. The building and the concrete slab were removed for off-Site disposal. The same demolition company then proceeded to break up the concrete sub-floor in the remainder of the petroleum-impacted area as indicated on figure 2. This area consisted of several layers of concrete extending down several feet, with each layer separated vertically by approximately one foot of soil. This part of the excavation did not go deep enough to encounter any contaminated soil. Once this area was broken up, some of this clean concrete was transported off-site for disposal and the remainder was stockpiled for use as future backfill.

Starting on June 23, 2008, excavation of the impacted area was started along the eastern edge by the Blackstone River and proceeded west towards the Blackstone Canal. The plan was to excavate a small area down to below groundwater, clean up any separate

phase product that may exist, backfill the hole, and move on to another area. During the entire excavation, all contaminated soils were stored on-Site on 6-mil poly sheeting. Each hole was dug to a depth of about 5 feet into groundwater, or 17 feet below grade, which was the extension limit of the excavator used. Groundwater depth was found to be the same as the river level throughout the entire excavation. As the excavation was completed below groundwater level, de-watering the hole became impossible due to the rapid rate of recharge from the surrounding groundwater. A 4-inch diaphragm pump and a vac-truck working together had no effect lowering the water levels in the holes. As oil contaminated soil was excavated from below groundwater, trapped oil was freed from the churned up gravel and floated to the surface of the water. This separate phase product was skimmed using a weir skimmer and pumped through a RIPDES (RI Pollutant Discharge Elimination System Permit # RIO-396) permitted treatment system consisting of an oil/water separator and a carbon treatment system. The clean effluent was then pumped into the nearby Blackstone Canal. Per the RIPDES permit, samples of both midstream and effluent water were regularly submitted for laboratory analysis to monitor the effectiveness of this system. These results were submitted to the RIDEM Office of Water Resources. In the course of the remediation a total of 7,540 gallons of water was pumped through the carbon treatment system and about 250 gallons of #6 fuel oil was recovered and disposed of off-site by Cyn Environmental of Stoughton, MA.

The soils encountered during the excavation were similar throughout the Site. These consisted of soil mixed with concrete and brick debris in the top 5 feet, followed by medium to coarse, sandy gravel from about 5 feet to 11 feet below grade, then larger river gravel with less sand below groundwater (river) level. At each stage of the excavation, soil samples were collected from the bottom of the hole. Samples AEG-201 through AEG-209 were submitted to a Rhode Island certified laboratory for analysis of total petroleum hydrocarbon (TPH) via Environmental Protection Agency (EPA) method 8100M. The location of each sample is shown on Figure 3 – Excavation Summary, and the analytical results are shown in Table 1 below. The final excavation was completed on July 15, 2008.

Table 1: Analytical Results of Soil Samples

Sample #	TPH (mg/kg)	RIDEM TPH GA-LC (mg/kg)	RIDEM TPH I/C DEC (mg/kg)
AEG-201	**2,830**	500	2,500
AEG-202	**10,000**	500	2,500
AEG-203	**4,620**	500	2,500
AEG-204	**1,360**	500	2,500
AEG-205	**1,700**	500	2,500
AEG-206	51.5	500	2,500
AEG-207	**899**	500	2,500
AEG-208	68.0	500	2,500
AEG-209	**957**	500	2,500

Bold indicates exceedence of RIDEM TPH GA-LC and/or TPH I/C DEC

The above table shows the analytical results for all soil samples taken during the excavation. For most of these samples, the concentrations are well above the applicable RIDEM GA Groundwater Leachability Criteria (GA-LC) as well as the Method 1 Industrial/Commercial Direct Exposure Criterion (I/C-DEC). A copy of the laboratory analytical report has been attached as Appendix A.

In the course of the excavation, approximately 882 tons of oil-contaminated soil was removed and stored on-site on top of and covered with 6-mil poly until such time as it could be transported off-site to a licensed disposal facility. On October 30, November 7 and November 10, 2008, the material was loaded onto trucks and transported to Environmental Soil Management Inc. (ESMI) in Loudon, New Hampshire for thermal destruction. A Copy of the Contaminated Soil Removal Records is attached as Appendix B and a photo log is attached as Appendix C.

Conclusion

This project was initiated due to the proximity of the release to the Blackstone River and the evidence of free mobile product in the subsurface. RIDEM required a comprehensive response action to remove impacted soil from the subsurface in an effort to prevent further migration toward the river. It is AEG's opinion that with the oil source long since removed and although some oil contaminated soil remains in the ground below the level of the excavation, this goal has been achieved and there appears to be no remaining risk of oil migrating to the Blackstone River from this property.

At this time AEG requests RIDEM to please provide a No Further Action (NFA) letter for this matter.

Upon your review please contact the undersigned with any questions or concerns at 401-732-7600.

Very truly yours,
Alliance Environmental Group, Inc.

Richard C. Hittinger
President

Peter Rooks
Environmental Engineer

Jacob H. Butterworth
Environmental Scientist

Attachments:

Figure 1	USGA Locus Map
Figure 2	Site Plan
Figure 3	Excavation Summaries
Appendix A	Soil Analytical Reports
Appendix B	Contaminated Soil Removal Records
Appendix C	Photo Log

cc: Bill Walker, FDS Industries
Mr. Frank Gardner, United States Environmental Protection Agency (USEPA)

Figure 1

USGS Locus Map



Alliance Environmental Group, Inc.
100 Jefferson Boulevard, Warwick RI 02888
Telephone: 401.732.7600; Fax: 401.732.7670

N

11/5/08

USGS LOCUS MAP
CARRINGTON STREET
LINCOLN, RI
AEG Proj. # 1418

File: 1418-05.Locus.dwg Drawn by: JHB Checked by: RCH

Figure 2

Site Plan


BLACKSTONE RIVER
FLOW DIRECTION
TP-101
TP-107
TP-102
TP-106
B-107/MW-104
104
TP-103
FORMER SMOKE STACK

Figure 3

Excavation Summary


BLACKSTONE RIVER
FLOW DIRECTION
[S AREA
MEDIATED
EPA
AEG-202
AEG-201
AEG-205
AEG-208
AEG-203
FORMER
BUILDING
LOCATION
AEG-204
AEG-206
AEG-207
FORMER
BUILDING
LOCATION
EXCAVATOR & TRUCK RAMP
EXISTING
BUILDING

Appendix A

Soil Analytical Report

ESS Laboratory

Division of Thielsch Engineering, Inc.

CERTIFICATE OF ANALYSIS

PROJECT NARRATIVE

Jacob H. Butterworth
Alliance Environmental Group
100 Jefferson Boulevard
Warwick, RI 02888

RE: Carrington St
ESS Laboratory Work Order Number: 0806426

This signed Certificate of Analysis is our approved release of your analytical results. These results are only representative of sample aliquots received at the laboratory. ESS Laboratory expects its clients to follow all regulatory sampling guidelines. Beginning with this Project Narrative, the entire report has been paginated. The ESS Laboratory Certifications sheet is the final report page. This report should not be copied except in full without the approval of the laboratory. Samples will be disposed of thirty days after the final report has been mailed. If you have any questions or concerns, please feel free to call our Customer Service Department.

Laurel Stoddard
Laboratory Director

Date: July 01, 2008

Analytical Summary
The project as described above has been analyzed in accordance with the ESS Quality Assurance Plan. This plan utilizes the following methodologies: US EPA SW-846, US EPA Methods for Chemical Analysis of Water and Wastes per 40 CFR Part 136, APHA Standard Methods for the Examination of Water and Wastewater, American Society for Testing and Materials (ASTM), and other recognized methodologies. The analyses with these noted observations are in conformance to the Quality Assurance Plan. In chromatographic analysis, manual integration may be used instead of automated integration because it produces more accurate results. All ICP Metals were analyzed using the established linear dynamic range to determine acceptable analytical results.

ESS Laboratory certifies that the test results meet the requirements of NELAC, except where noted within this project narrative.

Sample Receipt
The following sample(s) were received on June 27, 2008 for the analyses specified on the enclosed Chain of Custody Record.

Laboratory ID	Matrix	Client SampleID
0806426-01	Soil	AEG-201

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St

ESS Laboratory Work Order: 0806426

PROJECT NARRATIVE

No unusual observations noted.

End of Project Narrative.

ESS Laboratory

Division of Thielsch Engineering, Inc.

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-201
Date Sampled: 06/22/08 00:00
Percent Solids: 80
Initial Volume: 20.3
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0806426
ESS Laboratory Sample ID: 0806426-01
Sample Matrix: Soil
Analyst: SEP
Prepared: 06/27/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	Limit	DF	Analyzed
Total Petroleum Hydrocarbons	**2830**	mg/kg dry	92.4		2	06/30/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*84 %*		*40-140*

ESS Laboratory

Division of Thielsch Engineering, Inc.
185 Frances Avenue, Cranston, RI 02910-2211
Tel. (401) 461-7181 Fax (401) 461-4486
www.esslaboratory.com

CHAIN OF CUSTODY

Page ____ of ____

Turn Time: Standard Other ____
If faster than 5 days, prior approval by laboratory is required # ____
State where samples were collected from: MA (RI) CT NH NJ NY ME Other ____
Is this project for any of the following: MA-MCP Navy USACE Other ____

Reporting Limits

ESS LAB PROJECT ID: 08064126

Electronic Deliverable: Yes ___ No
Format: Excel ___ Access ___ PDF ✓ Other ____

Co. Name	Project #	Project Name (20 Char. or less)
AEG	418	Carrington St.

Contact Person	Address
Jacob H. Butterworth	100 Jefferson Blvd.

City	State	Zip	PO#
Warwick	RI	02886	

Telephone #	Fax #	Email Address
732-7600	732-7670	

ESS LAB Sample#	Date	Collection Time	COMP	GRAB	MATRIX	Sample Identification (20 Char. or less)	Pres Code	Number of Containers	Type of Containers	Write Required Analysis: 8260 MT
1	6/22/08	—		X	S	AEG-201	1	1	G	✓

Container Type: P-Poly G-Glass S-Sterile V-VOA | Matrix: S-Soil SD-Solid D-Sludge WW-Wastewater GW-Ground Water SW-Surface Water DW-Drinking Water O-Oil W-Wipes F-Filters

Cooler Present: ✓ Yes ___ No — Internal Use Only
Seals Intact: ___ Yes ___ No NA: ✓ [✓ Pickup
Cooler Temp: 4.8°C [ ] Technicians ____

Preservation Code: 1- NP, 2- HCl, 3- H_2SO_4, 4- HNO_3, 5- NaOH, 6- MeOH, 7- Asorbic Acid, 8- ZnAct, 9- ____

Sampled by: Jacob H. Butterworth

Comments: None

Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time
Jacob H. Butterworth	6/27/08 12:10	[illegible]	6/27/08 12:10	[illegible]	6/27/08 15:10	[illegible]	6/27/08 15:10
Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time

*By circling MA-MCP, client acknowledges samples were collected in accordance with MADEP CAM VII A

Please fax all changes to Chain of Custody in writing..

1 (White) Lab Copy 2 (Yellow) Client Receipt

10/26/04 A

R.I. ANALYTICAL
Specialists in Environmental Services

CERTIFICATE OF ANALYSIS

Alliance Environmental
Attn: Mr. Jacob Butterworth
100 Jefferson Boulevard
Suite 220
Warwick, RI 02888

Date Received: 6/30/08
Date Reported: 7/3/08
P.O. #: 1418
Work Order #: 0806-11459

DESCRIPTION: PROJECT #1418 CARRINGTON STREET

Subject sample(s) has/have been analyzed by our Warwick, R.I. laboratory with the attached results.

Reference: All parameters were analyzed by U.S. EPA approved methodologies.
The specific methodologies are listed in the methods column of the Certificate Of Analysis.

Data qualifiers (if present) are explained in full at the end of a given sample's analytical results.

Certification #: RI-033, MA-RI015, CT-PH-0508, ME-RI015
NH-253700 A & B, USDA S-41844

If you have any questions regarding this work, or if we may be of further assistance, please contact our customer service department.

Approved by:

Data Reporting

enc: Chain of Custody

R.I. Analytical Laboratories, Inc.

CERTIFICATE OF ANALYSIS

Alliance Environmental
Date Received: 6/30/08
Work Order #: 0806-11459

Approved by: _____
Data Reporting

Sample # 001
SAMPLE DESCRIPTION: AE6-202
SAMPLE TYPE: GRAB **SAMPLE DATE/TIME:** 6/27/2008

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE ANALYZED	ANALYST
TPH						
TPH GC/FID	10000	52	mg/kg dry	SW846 8100M	7/2/08	CDC
Moisture	12		%	SM2540 G.	7/2/08	CEC
Extraction date	Extracted			SW846 3545	7/1/08	MTS

CHAIN OF CUSTODY RECORD

R.I. Analytical Laboratories, Inc.

41 Illinois Avenue
Warwick, RI 02888
Tel: 800-937-2580
Fax: 401-738-1970

131 Coolidge St, Bldg. 2
Hudson, MA 01749
Tel: 888-228-3334
Fax: 978-568-0078

Date Collected	Time Collected	Field Sample Identification	Grab or Composite	# of Containers & Type [T]	Preservation Code [P]	Matrix Code [M]	8/10 m
6.27.08	—	AE6-202	G	1	NP	S	Q

Client Information

Company Name: Alliance Environmental
Address: 100 Jefferson Boulevard Suite 220
City / State / Zip: Warwick RI 02888
Telephone: 732-7600 Fax: 732-7670
Contact Person:

Project Information

Project Name: Carrington St.
P.O. Number: 1419 Project Number: 1418
Report To: Jacob H. Butterworth Phone: Fax:
Sampled by: JHB AE6
Quote No: Email address:

Relinquished By	Date	Time	Received By	Date	Time
[signature]	6.30.08	12:43	[signature]	6/30/08	12:43
[signature]	6/30/08	1250	[signature]	6/30/08	1250

Turn Around Time

- Normal — X EMAIL Report
- 5 Business days. Possible surcharge
- Rush _____ (business days)

Project Comments

Circle if applicable: GW-1, GW-2, GW-3, S-1, S-2, S-3 MCP Data Enhancement QC Package? Yes No

16.8

Lab Use Only

- Sample Pick Up Only
- RIAL sampled; attach field hours
- Shipped on ice

Workorder No: 0826-1459

Container Types: P=Poly, G=Glass, AG=Amber Glass, V=Vial, St=Sterile

Preservation Codes: NP=None, N=HNO_3, H=HCl, S=H_2SO_4, SH=NaOH, SB=$NaHSO_4$, M=MeOH, T=$Na_2S_2O_3$, Z=ZnOAc, I=Ice

Matrix Codes: GW=Groundwater, SW=Surface Water, WW=Wastewater, DW=Drinking Water, S=Soil, SI=Sludge, A=Air, B=Bulk/Solid, O=_____

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AE203-3 ft Below GW
Date Sampled: 07/02/08 00:00
Percent Solids: 92
Initial Volume: 19.3
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807070
ESS Laboratory Sample ID: 0807070-03
Sample Matrix: Soil
Analyst: ML
Prepared: 07/09/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	Limit	DF	Analyzed
Total Petroleum Hydrocarbons	4620	mg/kg dry	211		5	07/10/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*87 %*		*40-140*

ESS Laboratory

Division of Thielsch Engineering, Inc.
185 Frances Avenue, Cranston, RI 02910-2211
Tel. (401) 461-7181 Fax (401) 461-4486
www.esslaboratory.com

CHAIN OF CUSTODY

Page 1 of 1

Turn Time: X Standard Other ____
If faster than 5 days, prior approval by laboratory is required #____
State where samples were collected from: MA (RI) CT NH NJ NY ME Other ____
Is this project for any of the following: MA-MCP Navy USACE Other ____

Reporting Limits

ESS LAB PROJECT ID: 0807070

Electronic Deliverable ___ Yes ___ No
Format: Excel__ Access__ PDF__ Other ____

Co. Name	Project #	Project Name (20 Char. or less)
Alliance Environmental	1418-06	Carrington St.

Contact Person: Rich
Address:
City: State: Zip: PO#:
Telephone #: 732 7600 Fax #: Email Address:

ESS LAB Sample#	Date	Collection Time	COMP	GRAB	MATRIX	Sample Identification (20 Char. or less)	Pres Code	Number of Containers	Type of Containers	Write Required Analysis: TPH	PAH
1	7/3/08			X	WW	Mid point	2	1	G	X	X
2	7/3/08			X	WW	Effluent	2	1	G	X	X
3	7/2/08			X	S	AE203 - 3' below GW	1	1	G	X	

Container Type: P-Poly G-Glass S-Sterile V-VOA | Matrix: S-Soil SD-Solid D-Sludge WW-Waste Water GW-Ground Water SW-Surface Water DW-Drinking Water O-Oil W-Wipes F-Filters

Cooler Present ✓ Yes ___ No Internal Use Only
Seals Intact ___ Yes ___ No NA: ✓ [ ] Pickup
Cooler Temp: 4.6° [ ] Technicians

Preservation Code: 1- NP, 2- HCl, 3- H_2SO_4, 4- HNO_3, 5- NaOH, 6- MeOH, 7- Asorbic Acid, 8- ZnAct, 9- ____
Sampled by:
Comments:

Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time
Rick Hall			7/7/08 11:31		7/7/08 11:46		7-7-08 11:46
Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time

*By circling MA-MCP, client acknowledges samples were collected in accordance with MADEP CAM VII A

Please fax all changes to Chain of Custody in writing.

1 (White) Lab Copy 2 (Yellow) Client Receipt

10/26/04 A

ESS Laboratory

Division of Thielsch Engineering, Inc.

CERTIFICATE OF ANALYSIS

PROJECT NARRATIVE

Rich Hittinger
Alliance Environmental Group
100 Jefferson Boulevard
Warwick, RI 02888

RE: Carrington St
ESS Laboratory Work Order Number: 0807149

This signed Certificate of Analysis is our approved release of your analytical results. These results are only representative of sample aliquots received at the laboratory. ESS Laboratory expects its clients to follow all regulatory sampling guidelines. Beginning with this Project Narrative, the entire report has been paginated. The ESS Laboratory Certifications sheet is the final report page. This report should not be copied except in full without the approval of the laboratory. Samples will be disposed of thirty days after the final report has been mailed. If you have any questions or concerns, please feel free to call our Customer Service Department.

Laurel Stoddard
Laboratory Director

Date: July 16, 2008

Analytical Summary
The project as described above has been analyzed in accordance with the ESS Quality Assurance Plan. This plan utilizes the following methodologies: US EPA SW-846, US EPA Methods for Chemical Analysis of Water and Wastes per 40 CFR Part 136, APHA Standard Methods for the Examination of Water and Wastewater, American Society for Testing and Materials (ASTM), and other recognized methodologies. The analyses with these noted observations are in conformance to the Quality Assurance Plan. In chromatographic analysis, manual integration may be used instead of automated integration because it produces more accurate results. All ICP Metals were analyzed using the established linear dynamic range to determine acceptable analytical results.

ESS Laboratory certifies that the test results meet the requirements of NELAC, except where noted within this project narrative.

Sample Receipt
The following sample(s) were received on July 10, 2008 for the analyses specified on the enclosed Chain of Custody Record.

Laboratory ID	Matrix	Client SampleID
0807149-01	Soil	AEG-204
0807149-02	Soil	AEG-205
0807149-03	Soil	AEG-206
0807149-04	Soil	AEG-207
0807149-05	Soil	AEG-208

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St

ESS Laboratory Work Order: 0807149

PROJECT NARRATIVE

No unusual observations noted.

End of Project Narrative.

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-204
Date Sampled: 07/07/08 00:00
Percent Solids: 95
Initial Volume: 20.1
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807149
ESS Laboratory Sample ID: 0807149-01
Sample Matrix: Soil
Analyst: SEP
Prepared: 07/12/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	RI - IC DEC Limit	DF	Analyzed
Total Petroleum Hydrocarbons	1360	mg/kg dry	39.3	2500	1	07/14/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*111 %*		*40-140*

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-205
Date Sampled: 07/07/08 00:00
Percent Solids: 85
Initial Volume: 20.8
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807149
ESS Laboratory Sample ID: 0807149-02
Sample Matrix: Soil
Analyst: SEP
Prepared: 07/12/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	RI - IC DEC Limit	DF	Analyzed
Total Petroleum Hydrocarbons	1700	mg/kg dry	42.4	2500	1	07/14/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*115 %*		*40-140*

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-206
Date Sampled: 07/08/08 00:00
Percent Solids: 85
Initial Volume: 20.3
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807149
ESS Laboratory Sample ID: 0807149-03
Sample Matrix: Soil
Analyst: SEP
Prepared: 07/12/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	RI - IC DEC Limit	DF	Analyzed
Total Petroleum Hydrocarbons	51.5	mg/kg dry	43.5	2500	1	07/15/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*88 %*		*40-140*

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-207
Date Sampled: 07/08/08 00:00
Percent Solids: 89
Initial Volume: 20.1
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807149
ESS Laboratory Sample ID: 0807149-04
Sample Matrix: Soil
Analyst: SEP
Prepared: 07/12/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	RI - IC DEC Limit	DF	Analyzed
Total Petroleum Hydrocarbons	899	mg/kg dry	41.9	2500	1	07/14/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*83 %*		*40-140*

ESS Laboratory

Division of Thielsch Engineering, Inc.

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington St
Client Sample ID: AEG-208
Date Sampled: 07/09/08 00:00
Percent Solids: 84
Initial Volume: 20.3
Final Volume: 1
Extraction Method: 3546

ESS Laboratory Work Order: 0807149
ESS Laboratory Sample ID: 0807149-05
Sample Matrix: Soil
Analyst: SEP
Prepared: 07/12/08

8100M Total Petroleum Hydrocarbons

RI - IC DEC

Analyte	Results	Units	MRL	Limit	DF	Analyzed
Total Petroleum Hydrocarbons	68.0	mg/kg dry	44.0	2500	1	07/15/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*97 %*		*40-140*

ESS Laboratory

Division of Thielsch Engineering, Inc.
185 Frances Avenue, Cranston, RI 02910-2211
Tel. (401) 461-7181 Fax (401) 461-4486
www.esslaboratory.com

CHAIN OF CUSTODY

Page 1 of 1

Turn Time ___ Standard Other ___
If faster than 5 days, prior approval by laboratory is required #___
State where samples were collected from:
MA (RI) CT NH NJ NY ME Other ___
Is this project for any of the following:
MA-MCP Navy USACE Other ___

Reporting Limits

ESS LAB PROJECT ID: 0807149

Electronic Deliverable ___ Yes ___ No
Format: Excel ___ Access ___ PDF ___ Other ___

Co. Name: Alliance Environmental
Project #: 1418-06
Project Name (20 Char. or less): Carrington St.
Contact Person
Address
City State Zip
PO#
Telephone #
Fax #
Email Address

ESS LAB Sample#	Date	Collection Time	COMP	GRAB	MATRIX	Sample Identification (20 Char. or less)	Pres Code	Number of Containers	Type of Containers	Write Required Analysis: TPH 8100M
1	7/7/08			X	S	AEG-204	1	1	G	X
2	7/7/08			X	S	AEG-205	1	1	G	X
3	7/8/08			X	S	AEG-206	1	1	G	X
4	7/8/08			X	S	AEG-207	1	1	G	X
5	7/1/08			X	S	AEG-208	1	1	G	X

Container Type: P-Poly G-Glass S-Sterile V-VOA
Matrix: S-Soil SD-Solid D-Sludge WW-Waste Water GW-Ground Water SW-Surface Water DW-Drinking Water O-Oil W-Wipes F-Filters

Cooler Present ✓ Yes ___ No
Seals Intact ___ Yes ___ No NA: ✓
Cooler Temp: 4.0°c
Internal Use Only
[ ] Pickup
[ ] Technicians ___

Preservation Code: 1- NP, 2- HCl, 3- H_2SO_4, 4- HNO_3, 5- NaOH, 6- MeOH, 7- Asorbic Acid, 8- ZnAct, 9- ___
Sampled by:
Comments:

Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time
Rich Hitt	7/10/08 11:48	Ralph Brooks	7/10/08 11:48	Ralph Brooks	7/10/08 12:15	J Dawes	7/10/08 12:15
Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time

*By circling MA-MCP, client acknowledges samples were collected in accordance with MADEP CAM VII A

Please fax all changes to Chain of Custody in writing.

1 (White) Lab Copy 2 (Yellow) Client Receipt

10/26/04 A

ESS Laboratory

Division of Thielsch Engineering, Inc.

CERTIFICATE OF ANALYSIS

Client Name: Alliance Environmental Group
Client Project ID: Carrington Street
Client Sample ID: AEG-209 17 Below Grade
Date Sampled: 07/14/08 00:00
Percent Solids: 81
Initial Volume: 20.1
Final Volume: 1
Extraction Method: 3541

ESS Laboratory Work Order: 0807272
ESS Laboratory Sample ID: 0807272-03
Sample Matrix: Soil
Analyst: ML
Prepared: 07/18/08

8100M Total Petroleum Hydrocarbons

Analyte	Results	Units	MRL	Limit	DF	Analyzed
Total Petroleum Hydrocarbons	957	mg/kg dry	46.1		1	07/19/08

	%Recovery	Qualifier	Limits
Surrogate: O-Terphenyl	*94 %*		*40-140*

ESS Laboratory

Division of Thielsch Engineering, Inc.
185 Frances Avenue, Cranston, RI 02910-2211
Tel. (401) 461-7181 Fax (401) 461-4486
www.esslaboratory.com

CHAIN OF CUSTODY

Page 1 of 1

Turn Time: X Standard Other ____
If faster than 5 days, prior approval by laboratory is required #____
State where samples were collected from: MA (RI) CT NH NJ NY ME Other ____
Is this project for any of the following: MA-MCP Navy: USACE Other ____

Reporting Limits

ESS LAB PROJECT ID: 0807272

Electronic Deliverable ___ Yes ___ No
Format: Excel ___ Access ___ PDF ___ Other ____

Co. Name	Project #	Project Name (20 Char. or less)
Alliance Environmental	1418-06	Carrington Street

Contact Person	Address	
Peter Rooks	100 Jefferson Blvd.	

City	State	Zip	PO#
Warwick	RI	02888	

Telephone #	Fax #	Email Address
732-7600		prooks@allianceenvironmental.com

ESS LAB Sample#	Date	Collection Time	COMP	GRAB	MATRIX	Sample Identification (20 Char. or less)	Pres Code	Number of Containers	Type of Containers	Write Required Analysis: TPH	PAH
1	7/15/08			X	WW	Infeed	2	1	G	X	X
2	7/15/08			X	WW	Effluent	2	1	G	X	X
3	7/14/08			X	S	AEG-209 17' below grade	1	1	G	X	
4	7/15/08			X	S	AEG-Waste contaminated Soil	1	1	G	X	X

Container Type: P-Poly G-Glass S-Sterile V-VOA Matrix: S-Soil SD-Solid D-Sludge WW-Waste Water GW-Ground Water SW-Surface Water DW-Drinking Water O-Oil W-Wipes F-Filters

Cooler Present: Yes ___ No
Seals Intact: ___ Yes ___ No NA: ___
Cooler Temp: 4.0°c

Internal Use Only
[ ] Pickup
[ ] Technicians ____

Preservation Code: 1- NP, 2- HCl, 3- H_2SO_4, 4- HNO_3, 5- NaOH, 6- MeOH, 7- Ascorbic Acid, 8- ZnAct, 9- ____

Sampled by:

Comments:

Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time	Relinquished by: (Signature)	Date/Time	Received by: (Signature)	Date/Time
[signature]	7/17 1700	[signature]				[signature]	7/17/08 1500
[signature]	7/17 1917	[signature]	7/17/08 1515				

*By circling MA-MCP client acknowledges samples were collected in accordance with MADEP CAM VII A

Please fax all changes to Chain of Custody in writing.

1 (White) Lab Copy 2 (Yellow) Client Receipt

Appendix B

Contaminated Soil Removal Records

From Date: 10/27/2008
To Date: 10/31/2008

Invoicing Report

umber	Date	Truck	Net Tons	
ALLIANCE ENVIR. GROUP, INC.				Customer Number: AL10
OB #	6332			
3138	10/30/08	DEY1	30.16	tn
3140	10/30/08	WEBB01	35.76	tn
48145	10/30/08	DG03	38.28	tn
48146	10/30/08	DG08	35.51	tn
3148	10/30/08	GLOBALR	36.50	tn
3149	10/30/08	MYSTIC31	36.66	tn
48177	10/30/08	WEBB01	35.94	tn
3178	10/30/08	DEY1	33.01	tn
3190	10/30/08	DG03	34.62	tn
48192	10/30/08	GLOBALR	36.96	tn
48193	10/30/08	DG08	33.25	tn
3194	10/30/08	MYSTIC31	38.96	tn
3195	10/30/08	MYSTIC26	39.28	tn
48196	10/30/08	MYSTIC26	43.18	tn
			508.07	tn
			#6 FUEL OIL	
ALLIANCE ENVIR. GROUP, INC.			**508.07**	tn

From Date: 11/3/2008

To Date: 11/7/2008

Invoicing Report

umber	Date	Truck	Net Tons	
LIANCE ENVIR. GROUP, INC.				Customer Number: AL10
B #	6332			
3435	11/7/08	WEBB01	35.02	tn
48437	11/7/08	MYSTIC33	39.35	tn
48438	11/7/08	MYSTIC28	38.97	tn
3440	11/7/08	GLOBALR	36.65	tn
48466	11/7/08	WEBB01	37.95	tn
48467	11/7/08	MYSTIC33	38.74	tn
8468	11/7/08	MYSTIC28	38.99	tn
8477	11/7/08	GLOBALR	36.99	tn
			302.66	tn

#6 FUEL OIL

LLIANCE ENVIR. GROUP, INC. **302.66** tn

From Date: 11/10/2008
To Date: 11/14/2008

Invoicing Report

imber	Date	Truck	Net Tons	
IANCE ENVIR. GROUP, INC.				Customer Number: AL10
B.#: 6332				
502	11/10/08	MYSTIC33	32.65	tn
504	11/10/08	MYSTIC28	38.37	tn
			71.02	tn
			#6 FUEL OIL	
LIANCE ENVIR. GROUP, INC:			71.02	tn

Appendix C

Photo Log

Photo 1: View of excavation with oil layer before skimming, in area of sample AEG-205.

Photo 2: View of excavation in area of sample AEG-206. No visible oil on water.



Photo 3: View of excavation in area of samples AEG-208 & AEG-209. Note oil layer and oil skimmer in use (circled).



Photo 4: View of vac truck, oil/water separator, and water filtration system trailer.

Photo 5: Backfilling of excavation after completion of cleanup.



Photo 6: View of contaminated soil pile. Removed to ESMI disposal facility November 2008

PCL XL error

Subsystem: GE_VECTOR

Error: GEEmptyClipPath Warning: IllegalMediaSize